

# *Inspection Photos*

*API#103-40209*

*Operator: Unknown (Pleasant Valley Oil)*

*Inspection #: 692400868*

*Inspection Date 3/29/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Photo#1:**  
There is No Evidence of the Well.

March, 29, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Pleasant Valley Unknown API#103-40209





**Photo#2:**

There is No Evidence of the Well. Town of Rangely Irrigation Pump to left of Jeep.

March, 29, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Pleasant Valley Unknown API#103-40209





**Photo#3:**  
There is No Evidence of the Well

March, 29, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Pleasant Valley Unknown API#103-40209





**Photo#4:**

Only item seen that might be related to a Well; though this area is used as dump area; and scraping area from old buildings.

March, 29, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Pleasant Valley Unknown API#103-40209





Photo#5:  
Chevron Injection well 325ft to NW; API#103-05453.

March, 29, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Pleasant Valley Unknown API#103-40209