

Caerus Piceance LLC
Api # 05-045-10650
Inspection # 696600037



Photo at entrance to location.

Caerus Piceance LLC
Api # 05-045-10650
Inspection # 696600037



Signs at separators



Photo at entrance of location

Caerus Piceance LLC
Api # 05-045-10650
Inspection # 696600037



Tank battery



Tank Battery labels

Caerus Piceance LLC
Api # 05-045-10650
Inspection # 696600037



Stainless tubing sticking out of the ground



Unused equipment on location