

Caerus Piceance LLC  
Api # 05-045-11763  
Inspection # 696600044



Photo at SW entrance of location

Caerus Piceance LLC  
Api # 05-045-11763  
Inspection # 696600044



Photo from NE entrance.

Tank Battery

Caerus Piceance LLC  
Api # 05-045-11763  
Inspection # 696600044



2 wellheads on location



Separators