

# *Inspection Photos*

*Loc#441601*

*Operator: XTO*

*Inspection Number: 692400944*

*Inspection Date: 5/2/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to North.

May 2, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: XTO RNPU Loc#441601





Photo#2:

There is a Lack of BMPs on Access road at North corner of site.

May 2, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources


Inspection Photos: XTO RNPULoc#441601





Photo#3:  
Stockpiles have no BMPs.

May 2, 2019



Photo#4:  
Stockpiles have no BMPs.





**Photo#5:**  
The stormwater controls on the Original section of site are functioning.

May 2, 2019



**Photo#6:**  
The stormwater controls on the Original section of site are functioning.