

Inspection Photos

Loc#436196

Operator: Ursa

Inspection Number: 692400829

Inspection Date: 4/24/2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Eight tanks stored in area, East of, & adjacent to
access road entry. View to Southwest.

April 24, 2019



Photo#2:
Eight tanks stored in area, East of, & adjacent to
access road entry View to Southeast.



Photo#3:
View over access road entry to South. Emerging vegetation can be seen.

April 24, 2019




Photo#4:
View over Location to Northeast.



Photo#5:
Repairs have been made to BMPs.

April 24, 2019



Photo#6:
Repairs have been made to BMPs.



Photo#7:
Sediment migration and erosion should be closely monitored.

April 24, 2019



Photo#8:
Sediment migration and erosion should be closely monitored.