

Inspection Photos  
Operator: Aramark  
Location/API #: 083-05222  
Date: 4-26-2019



Photo 1. View of fencing around well.



Photo 2. View of impacted material in barrels that needs to be removed and properly disposed of.