

Inspection Photos
Operator: Noel Reynolds
Location/API #: 067-05448
Date: 4-30-2019



Photo 1. View of the wellhead still in place facing westward. Electrical box documented from previous inspection is no longer present.



Photo 2. View of area south of the wellhead area that appears impacted by produced fluid or compacted. Vegetation in this area is largely annual weeds such as claspig pepperweed (*Lepidium perfoliatum*) and cheatgrass (*Bromus tectorum*).