

Inspection Photos
Location Name: Mutual 01-17H
Location ID: 324757



Photo 1. Crude oil tank with no containment.



Photo 2. Operational debris.

Inspection Photos
Location Name: Mutual 01-17H
Location ID: 324757



Photo 3. Separator stored on location.



Photo 4. Operational debris.

Inspection Photos
Location Name: Mutual 01-17H
Location ID: 324757



Photo 5. Operational debris.



Photo 6. Non reportable spill - stained soil and free product.

Inspection Photos
Location Name: Mutual 01-17H
Location ID: 324757



Photo 7. Movement of product from source of spill.



Photo 8. Non reportable spill - stained soil.

Inspection Photos
Location Name: Mutual 01-17H
Location ID: 324757



Photo 9. Stained soil at loadout in battery berm.



Photo 10. Vehicle tracking leaving location.

Inspection Photos
Location Name: Mutual 01-17H
Location ID: 324757



Photo 11. Vehicle tracking off of location onto Colorado State Highway 14 going north.



Photo 12. Vehicle tracking off of location onto Colorado State Highway 14 going south.