

Inspection Photos

Loc#336023

Operator: Ursa

Inspection Number: 692400936

Inspection Date: 4/26/2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

April 26 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Hangs A Pad Loc#336023



Photo#2:
Unmarked Anchor.

April 26 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Hangs A Pad Loc#336023