

Inspection Photos  
Location Name: TOP GEAR 14-21  
API #: 05-071-07602  
INSP. #:695100601



PHOTO 1: LOCATION

PHOTO 2: WELL SIGN/ OPERATOR ON POSTED WELL SIGN IS INACCURATE **Install sign to comply with Rule 210.b.**

## Inspection Photos

Location Name: TOP GEAR 14-21

API #: 05-071-07602

INSP. #:695100601



**PHOTO 3: PIT IS PULL ALMOST RUNNING OVER THE EDGE. THERE IS NO 2' FREEBOARD MARKER. Lower fluid level so at least two feet of freeboard exists per Rule 902.b. INSTALL FREEBOARD MARKER.**

**PHOTO 4: IMPACTED SOIL NEAR WELLHEAD NO LEAK OBSERVED AT TIME OF INSPECTION Comply with Rule 603.f .**