

Inspection Photos

Location BMC D Pad

Location # 446582



Photo 1
BMC D Pad



Photo 2
Stained surfaces around wells and in cellars.

Inspection Photos

Location BMC D Pad

Location # 446582



Photo 3

Stained surfaces around wells and in cellars.



Photo 4

Stained surfaces around wells and in cellars.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location BMC D Pad

Location # 446582



Photo 5

Stained surfaces around wells and in cellars.



Photo 6

Stained surfaces around wells and in cellars.