

Inspection Photos
Location Name: Detterer FD 24-21D
Location ID: 428879



Photo 1 – Non know E & P substance is seeping to surface



Photo 2 – Area of non know substance around wellhead.

Inspection Photos
Location Name: Detterer FD 24-21D
Location ID: 428879



Photo 3 – Non know E & P substance is seeping to surface



Photo 4 – Wellhead Signage is incorrect.

