

Inspection Photos
Location Name: UPRR-Habel 1-35
Location ID: 319728



Pic 1



Pic 2 no cap on load line

Inspection Photos
Location Name: UPRR-Habel 1-35
Location ID: 319728



Pic 3



Pic 4 unused tubing and rods, stained soil.