

**Inspection Photos**  
**Location name: Puckett 14-6D**  
**Location id. # 334977**



**Photo 1**



**Photo 2**

**Secondary containment is full of fluid.**



**Inspection Photos**  
**Location name: Puckett 14-6D**  
**Location id. # 334977**



**Photo 3**  
**Secondary containment is full of fluid.**



**Photo 4**  
**Secondary containment is full of fluid.**





# Inspection Photos

Location name: Puckett 14-6D  
Location id. # 334977



**Photo 5**  
**Labeling satisfactory**



**Photo 6**  
**Labeling satisfactory**



**Inspection Photos**  
**Location name: Puckett 14-6D**  
**Location id. # 334977**



**Photo 7**  
**Labeling satisfactory**



**Photo 8**  
**Labeling satisfactory**

