

Laramie Energy LLC  
Api # 05-077-09467  
Inspection # 696600050



Photo at entrance.

**Laramie Energy LLC**  
**Api # 05-077-09467**  
**Inspection # 696600050**



**Wellhead**



**Tank Battery**



**Laramie Energy LLC**  
**Api # 05-077-09467**  
**Inspection # 696600050**



**Silt fence in need of maintenance.**



**Berm in need of repair, erosion moving soil from location.**



**Laramie Energy LLC**  
**Api # 05-077-09467**  
**Inspection # 696600050**



**Berm has been damaged, in need of maintenance.**



**Berm has been compromised and in need of maintenance.**



**Laramie Energy LLC**  
**Api # 05-077-09467**  
**Inspection # 696600050**



**Close up of Berm damage . Storm water erosion from damaged berm shows erosion moving down hillside**



**Storm water erosion from damaged berm, Shown is erosion moving down hillside**