

Final Reclamation Inspection

May 6, 2019

Operator: HARSH INTERNATIONAL INC - 38470

API #: 05-123-11416

Inspection Document #: 697500074

Weld County, CO

SENE Section 6 T6N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HARSH #1
API #: 05-123-11416



Photo 1. Photo taken from a portion of the access road, facing South. Access road is evident and has not been reclaimed per Rule 1004. It does not appear that the Operator has performed final reclamation activities throughout the access road. Reference area vegetation consists mostly of Crested wheatgrass and Smooth brome.

Inspection Photos
Location Name: HARSH #1
API #: 05-123-11416



Photo 2. Photo taken from another portion of the access road, facing South. See comments under Photo 1.

Inspection Photos
Location Name: HARSH #1
API #: 05-123-11416



Photo 3. Photo taken from the tank battery location, facing South. Operator has failed to perform final reclamation activities at the tank battery location. Vegetation mainly consists of Cheatgrass, Kochia and Field bindweed, all undesirable species.

Inspection Photos
Location Name: HARSH #1
API #: 05-123-11416



Photo 4. Photo taken from the tank battery location. Photo illustrates gravel which has not been removed from location and Cheatgrass.

Inspection Photos
Location Name: HARSH #1
API #: 05-123-11416



Photo 5. Photo taken from the southeastern tank battery, facing North. Photo contrasts the reference area vegetation with the tank battery vegetation.




Photo 6. Photo taken from the southeastern tank battery, facing West. See comments under Photo 5.

Inspection Photos
Location Name: HARSH #1
API #: 05-123-11416



Photo 7. Reference photo taken north of the tank battery location, facing East.