

Inspected Facilities

Facility ID: 256762 Type: WELL API Number: 123-19922 Status: SI Insp. Status: PA

Workover

Comment: Rig Basic 1662

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>On Wednesday, May 8, 2019 at 12:19, I, Craig Carlile conducted an on-site inspection at: 05-123-19922 Operated by: Anadarko While there I observed: PA process. Crew awaiting wireline truck to set CIBP at 6970 ft. Anticipate balanced plug to be placed on following day Company representative on location: Traux Deal Possible compliance issues observed: None: ? This is a summary of the inspection report.</p>	carlilec	05/08/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690003511	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4817947