

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2019

Submitted Date:

05/08/2019

Document Number:

694400153**FIELD INSPECTION FORM**

Loc ID 440858 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1001 17TH STREET #2000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@gwogco.com	All Inspections
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440858	LOCATION	AC			-	Simpson FD Pad 15-219HN	AC

General Comment:

Inspected Facilities			
Facility ID: <u>440858</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AC</u> Insp. Status: <u>AC</u>
Producing Well			
Comment: <u>AC</u>			
Corrective Action:		Date:	
Complaint			
Comment:	<u>Inspection in response to complaint. 18#200447246</u> <u>Field Inspector Assigned: Adam Kraich</u> <u>Complaint Received:</u> <u>Date: 5/2/2019</u> <u>Complaint Contacted:</u> <u>Date: 5/2/2019 @8:52</u> <u>Location #: 440858</u> <u>Inspection Document #: 694400153</u> <u>Nature of complaint: Noise</u> <u>Field Inspector Actions:</u> <u>On 5/2/2019, I received a complaint concerning low frequency (C-Scale) noise coming from the Simpson FD location, owned and operated by Great Western Oil & Gas Company.</u> <u>On 5/2/2019, I set a continuous sound monitor 25 from the residence as guided by rule 802.d. I began the sound audit 5/2/2019 @ approximately 9:52am. The audit was concluded on 5/6/2019 at approximately 8:47am. LEQ averages are isolated to nighttime hours only (7am to 7pm). Additionally, the hours from 4:30am to 7:00am are excluded from the study and LEQ averages due to wind speeds beyond those defined on rule 802.</u> <u>LEQ 2 average over the course of the audit is observed at 70.7DB. This indicates noncompliance under rule 802.d.</u> <u>See inspection document for corrective action detail.</u> <u>All information reviewed and site inspection information were submitted to the complaint specialist for further review.</u>		
Corrective Action:	<u>Comply with rule 802.d</u>		Date: <u>05/13/2019</u>

COGCC Comments		
Comment	User	Date
<u>Inspection in response to complaint.</u>	kraicha	05/08/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694400154	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818014
694400155	Waether Data	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818015
694400156	Sound Audit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4818016