

Inspection Photos
Location Name: Leroy McCaw B #2
API: 05-067-08910



Leroy McCaw B #2 location photo.



Leroy McCaw B #2 production equipment.

Inspection Photos
Location Name: Leroy McCaw B #2
API: 05-067-08910



Stained gravel beneath truck load out valve for PBV.



Stained soil near compressor.