

# Inspection Photos

5/07/2019

Operator: GRAND MESA OPERATING CO #  
35080

Location ID: 463974

Inspection Doc. Number: 696200005  
Lincoln County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 463974



**Photo 1:** Photo taken from the south end of the location, facing west. Photos 1-4 provide an overview of the location and construction in process from west, northwest, northeast to east. Photos also show Operator has installed surface roughening along the perimeter of the disturbance area.



## Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 463974



**Photo 2:** See comment under photo 1.



Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 463974



**Photo 3:** See comment under photo 1.



Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 463974



**Photo 4:** See comment under photo 1.

## Inspection Photos


Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 463974



**Photo 5:** Photo taken from west end of the location. Photo shows operator is salvaging ~1 foot of soil (including topsoil) from the location.

**Inspection Photos**  
**Operator Name: GRAND MESA OPERATING CO # 35080**  
**Location ID: 463974**



**Photo 6:** Photo shows inspector mapped the location with a Trimble GPS device and determined a disturbance area of 4.1 acres at time of inspection.