

Inspection Photos
Operator: Kinder Morgan
Location/API #: 033-06078
Date: 5-7-2019



Photo 1. View of the project area from the southwestern corner facing center. Well pad is not reclaimed.



Photo 2. View of the southern project area from the southwestern corner facing eastward.