

Inspection Photos
Operator: Red Mesa
Location/API #: 067-06382
Date: 5-1-2019



Photo 1. View of the project area facing northwestward.



Photo 2. View of the eastern project area from the southeastern edge facing northward. Vegetation within the project area is weedy and largely comprised of Russian knapweed (*Acroptilon repens*) and cranesbill (*Erodium cicutarium*).