

Inspection Photos  
Location Name: IGE #140  
API: 05-067-09895



IGE #140 pump jack with stained soil around wellhead.



IGE #110 pump jack.

**Inspection Photos**  
**Location Name: IGE #140**  
**API: 05-067-09895**



**Harmon 1A wellhead.**



**Stained soil along western side of IGE #140 pump jack.**

**Inspection Photos**  
**Location Name: IGE #140**  
**API: 05-067-09895**



**Drip pot on drop out tank.**



**IGE #110 and Harmon #1A production equipment.**