

Inspection Photos

Location Name: DOE 9-17 & Spill/Release ID: 464273

Inspection Date: 5/6/2019



Photo #1 – Aerial of spill location (COGIS Maps). Black drop indicates location of the spill, red line represents the approximate distance from the spill to the arroyo (~42 feet)



Photo #2 – Two Excavations south of the leak, oily stained sidewalls.



Inspection Photos

Location Name: DOE 9-17 & Spill/Release ID: 464273

Inspection Date: 5/6/2019



Photo #3 – Compromised tank battery with the two excavations and the arroyo (south, ~42 feet)



Photo #4 – A 1” stick plugging pin hole sized leak. Excavations to the south of the leak. Oily stained soil located beneath the leak.



Location Name: DOE 9-17
Spill/Release ID: 464273
Inspection Date: 5/6/2019



Photo #5 – View of all three tank batteries

