

Inspection Photos

API: 05-055-06270

Operator: PETROGLYPH OPERATING CO

Inspection Date: 5/6/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-055-06270 | Date: 5/6/2019

Inspection Photos



Photo 1. There is an erosion channel along the access road near the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06270 | Date: 5/6/2019

Inspection Photos



Photo 2. Facing southwest toward the location. The vegetation appears to be fully established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06270 | Date: 5/6/2019

Inspection Photos



Photo 3. Facing west toward the reclaimed location. Vegetation appears to be established with Spocry, Passmi, and other desirable species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06270 | Date: 5/6/2019