

Inspection Photos

5/06/2019

Operator: OILFIELD SALVAGE & SERVICE CO -
65550

Location ID: 311709

Inspection Doc. Number: 696200013
Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator Name: OILFIELD SALVAGE & SERVICE CO - 65550
Location ID: 311709



Photo 1: Photo taken from the northwest end of the location, facing east. Photo shows that location remains predominantly bare and exposed soil. Straw wattle BMPs remain insufficient and have not been installed in accordance with good engineering practices. No additional reclamation or stormwater management appears to have been conducted per corrective actions.

Inspection Photos

Operator Name: OILFIELD SALVAGE & SERVICE CO - 65550

Location ID: 311709



Photo 2: Photo taken from the northwest end of the location, facing south. See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: OILFIELD SALVAGE & SERVICE CO - 65550

Location ID: 311709



Photo 3: Photo taken from the salt kill area of the location. Photo shows that location remains predominantly bare and exposed soil. No additional reclamation or stormwater management appears to have been conducted per corrective actions.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: OILFIELD SALVAGE & SERVICE CO - 65550

Location ID: 311709



Photo 4: Photo taken from the north end of the location, facing south. Photo shows the erosion degradation on the location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: OILFIELD SALVAGE & SERVICE CO - 65550

Location ID: 311709



Photo 5: Photo taken from the location, facing north. Photo shows straw wattle BMPs are not in proper functioning condition, and are insufficient. Photo also shows the erosion degradation on the location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: OILFIELD SALVAGE & SERVICE CO - 65550

Location ID: 311709



Photo 6: Photo taken from the location, facing south. See comments under photo 5.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: OILFIELD SALVAGE & SERVICE CO - 65550

Location ID: 311709



Photo 7: Photo taken from the south end of the location, facing south. See comments under photo 5



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: OILFIELD SALVAGE & SERVICE CO - 65550

Location ID: 311709



Photo 8: Photo taken from the south end of the location, facing west. Photo shows areas of sediment deposition due to stormwater runoff from the location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: OILFIELD SALVAGE & SERVICE CO - 65550

Location ID: 311709



Photo 9: Photo taken from the south end of the location, facing south. Photo shows areas of sediment deposition due to stormwater runoff from the location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: OILFIELD SALVAGE & SERVICE CO - 65550

Location ID: 311709



Photo 10: Photo taken from the north end of the location. Photo shows what appears to be a Scotch Thistle rosette growing on location. This is a Colorado State listed noxious weed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources