

Inspection Photos
Location Name: Ignacio 33-8 #2
API: 05-067-05508



Pit Facility ID #105402 excavation.

Excavation awaiting confirmation sample results prior to backfilling with stock piled fill dirt.

Inspection Photos
Location Name: Ignacio 33-8 #2
API: 05-067-05508



Ignacio 33-8 #2 location photo showing proximity of Pit Facility ID #105402 to production equipment and wellhead.



Stockpiled fill dirt for Pit ID #105402.