

Inspection Photos

5/07/2019

Operator: VERDAD RESOURCES LLC # 10651

Location ID: 456879

Inspection Doc. Number: 696200025

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator Name: VERDAD RESOURCES LLC # 10651

Location ID: 456879



Photo 1: Photo taken from the location facing west. Photo shows construction activities appear to have been conducted on the access road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: VERDAD RESOURCES LLC # 10651

Location ID: 456879



Photo 2: Photo taken from the location, facing south. Photo shows a soil stockpile, possibly from the access road.



Inspection Photos

Operator Name: VERDAD RESOURCES LLC # 10651

Location ID: 456879



Photo 3: Photo shows equipment mobilization. No construction activities appear to have begun on the location.



Inspection Photos
Operator Name: VERDAD RESOURCES LLC # 10651
Location ID: 456879



Photo 4: Photo of access road east towards location.

Inspection Photos

Operator Name: VERDAD RESOURCES LLC # 10651

Location ID: 456879



Photo 5: Photo of culvert at access road entrance.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources