

COMPLIANCE FOLLOW UP FORM

INFORMATION

Name colen@horizonenvservices.com
Date Mon Apr 29 2019
Well Name LEMON GAS UNIT H 3
API Number 50670926800
Select State Colorado
Work type COGCC Inspection AR
Action Complete Compliance Inspection Actions
Clean Up Weed Debris

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos

Completed work description



Selectively sprayed thistle population on southern part of reclamation area.