

COMPLIANCE FOLLOW UP FORM

INFORMATION

Name colen@horizonenvservices.com
Date Mon Apr 29 2019
Well Name LEMON GAS UNIT G 1
API Number 50670699100
Select State Colorado
Work type COGCC Inspection AR
Action Complete Compliance Inspection Actions
Other

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Completed work description

Selectively sprayed musk thistle populations.