

Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	May 2, 2019 10:11:25 AM MDT
Server Receive Date:	May 2, 2019 10:12:42 AM MDT
Reference Number:	20190502-18105234294
Location:	102 Prospect Dr, Durango, CO 81303, USA May 2, 2019 10:11:10 AM MDT [View Map]

Information

Name	colen@horizonenvservices.com
Date	May 2, 2019
Well Name	LUNT GAS UNIT 19-01 1
API Number	50670665900
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris

Picture North to South



Picture South to North



Picture East to West

