



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	May 2, 2019 3:30:16 PM MDT
Server Receive Date:	May 2, 2019 3:31:44 PM MDT
Reference Number:	20190502-18105276157
Location:	2099 Co Rd 300, Durango, CO 81303, USA May 2, 2019 3:31:23 PM MDT [View Map]

Information

Name	colen@horizonenvservices.com
Date	May 2, 2019
Well Name	PHILLIPS A 3R2
API Number	50670993100
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris

Picture North to South



Picture South to North



Picture East to West



Additional photos

