

County: Boulder

Township: 2N **Range:** 69W **Section:** 17 **QQ:** SENW

Original Latitude/ Longitude: 40.139766 / -105.142631

Updated Latitude/ Longitude: /

Basis for Location Change:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|-----------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: NA | Date: NA |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 578534 | Date: 6/5/1995 |
| | Doc #: 500137178 | Date: 4/19/1994 |
| | Doc #: | Date: |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> | Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date:

Timing of Pit Closure:

Well PA 5/1/1995, Passed PA inspection 6/5/1995.

Pit Status Review Summary:

Based on records review any pits on location were replaced by a cement water vault by the 4/19/1994 inspection. Well was plugged and passed final inspection 6/5/1995. Pit status has been changed to Closed.