

Inspection Photos
Location Name: ARGON 43-31
API #: 05-071-09823
INSP. #:695100628



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN



Inspection Photos
Location Name: ARGON 43-31
API #: 05-071-09823
INSP. #:695100628



PHOTO 3: UNUSED EQUIPMENT/ SOUND WALLS IN DISREPAIR.
COMPLY WITH RULE 603.f. REPAIR SOUND WALLS. CA DATE
6/10/19



PHOTO 4: UNUSED EQUIPMENT/ SOUND WALLS IN DISREPAIR.
COMPLY WITH RULE 603.f. REPAIR SOUND WALLS. CA DATE
6/10/19

Inspection Photos
Location Name: ARGON 43-31
API #: 05-071-09823
INSP. #:695100628



**PHOTO 5: UNUSED EQUIPMENT/ SOUND WALLS IN DISREPAIR.
COMPLY WITH RULE 603.f. REPAIR SOUND WALLS. CA DATE
6/10/19**



**PHOTO 6: UNUSED EQUIPMENT/ SOUND WALLS IN DISREPAIR.
COMPLY WITH RULE 603.f. REPAIR SOUND WALLS. CA DATE
6/10/19**

Inspection Photos
Location Name: ARGON 43-31
API #: 05-071-09823
INSP. #:695100628



**PHOTO 7: UNUSED EQUIPMENT OFF THE EAST EDGE OF
LOCATION. COMPLY WITH RULE 603.f. CA DATE 6/10/19**