

Inspection Photos
Location Name: CACHE-66N63W /17NENW
Location #: 309865



Photo #1
Cache 17-52 (05-123-25485) Wellsite
Shut-In | SI



Photo #2
Cache 17-52, 17-21 Battery
Shut-down

Inspection Photos
Location Name: CACHE-66N63W /17NENW
Location #: 309865



Photo #3
Cache 17-52, 17-21 Battery
Battery sign – Incorrect Wells listed
from prior FIR



Photo #4
Cache 17-52, 17-21 Battery
Battery sign - Corrected

Inspection Photos
Location Name: CACHE-66N63W /17NENW
Location #: 309865



Photo #5
Cache 17-52, 17-21 Battery
Produced H2O vault– Incorrect Capacity posted
from prior FIR



Photo #6
Cache 17-52, 17-21 Battery
Produced H2O vault– Correct Capacity posted

Inspection Photos
Location Name: CACHE-66N63W /17NENW
Location #: 309865



Photo #7
Cache 17-52, 17-21 Battery
West Prod Tank – Contents-Capacity NOT posted
from prior FIR




Photo #8
Cache 17-52, 17-21 Battery
West Prod Tank – Contents-Capacity NOW posted
Faintly Legible