

Inspection Photos

5/10/2019

Operator: PCR OPERATING LLC - 10657

Location ID: 454195

Inspection Doc. Number: 696200040

Morgan County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 454195



Photo 1: Photo taken from the northeast end of the tank battery, facing southwest. Photo shows insufficient signage/labeling on tanks in accordance with 210.d

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 454195



Photo 2: Photo taken from the east end of the tank battery, facing south. Photo shows insufficient secondary containment at tanks.

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 454195



Photo 3: Photo taken from the west end of the tank battery, facing southeast. Photo shows insufficient secondary containment at tanks. Photo shows insufficient signage/labeling on tanks in accordance with 210.d. Photo also shows insufficient secondary containment at tanks.

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 454195



Photo 4: Photo taken from the south end of the tank battery, facing northeast. Photo shows insufficient secondary containment at tanks. Photo shows insufficient signage/labeling on tanks in accordance with 210.d. Photo also shows insufficient secondary containment at tanks.

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 454195



Photo 5: Photo taken from the west end of the location. Photo of various trash debris observed on location.

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 454195



Photo 6: Photo taken from the west end of the location. Photo of shows meter run. Inspector audibly detected what appear to be gas freely venting from meter run. Inspector confirmed with PCR that gas venting was being conducted.

