

Inspection Photos

Loc#421223

Operator: Ursa

Inspection Number: 692400939

Inspection Date: 4/26/2019





Photo#1:
Overview of Location.

April 26 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa McLin A Loc#421223



Photo#2:
Weedy area where water pools at Southeast corner of Pad.

April 26 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa McLin A Loc#421223



Photo#3:
Interim Reclamation areas appear weedy with new & old growth.

April 26 2019