

STATE OF COLORADO  
OIL AND GAS CONSERVATION COMMISSION  
DEPARTMENT OF NATURAL RESOURCES

SUBMIT ORIGINAL AND 1 COPY



00496605

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir  
(See APPLICATION FOR PERMIT - " for such proposals )

FEDERAL INDIAN OR STATE LEASE NO.

N/A

☒ OIL WELL ☐ GAS WELL ☐ COALBED METHANE ☐ INJECTION WELL ☐ OTHER

PERMIT NO.

87-439

NAME OF OPERATOR

Union Pacific Resources Company

APPROV.

05-017-6665

ADDRESS OF OPERATOR

P.O. Box 7 MS 3407

WELL NAME

Arapahoe Unit

CITY STATE ZIP CODE

Fort Worth, TX 76101-0007

WELL NUMBER

#147

LOCATION OF WELL (Report location clearly and in accordance with any State requirements  
See and space if below )

660' FSL & 660' FWL

FIELD OR WILDCAT

Arapahoe

As proposed plug zone

same

12 COUNTY

Cheyenne

11 QTR QTR SEC. T.R. AND MERIDIAN

SWSW Sec. 22-14S-42W

Check Appropriate Box To Indicate Nature of Notice, Report or Notification

13A. NOTICE OF INTENTION TO:

- ☐ PLUG AND ABANDON
- ☐ MULTIPLE COMPLETION
- ☐ COMMINGLED ZONES
- ☐ FRACTURE TREAT
- ☐ REPAIR WELL
- ☐ OTHER

13B. SUBSEQUENT REPORT OF:

- ☐ FINAL PLUG AND ABANDONMENT  
(SUBMIT 3RD PARTY CEMENT VERIFICATION  
AND JOB LOG)
- ☐ ABANDONED LOCATION (WELL NEVER DRILLED -  
SITE MUST BE RESTORED WITHIN 6 MONTHS)
- ☐ REPAIRED WELL
- ☐ OTHER

\* Use Form 3 - Well Completion or Recompletion Reports and Log  
for subsequent reports of Multiple Commingled Completions  
and Recompletions.

13C. NOTIFICATION OF:

- ☒ SHUT-IN, TEMPORARILY ABANDONED  
(DATE 12-28-91 )  
(REQUIRED EVERY 6 MONTHS)
- ☐ PRODUCTION RESUMED  
(DATE )
- ☐ LOCATION CHANGE (SUBMIT NEW PLAT)
- ☐ WELL NAME CHANGE
- ☐ OTHER

DESCRIBE PROPOSED OR COMPLETED OPERATIONS ON THIS FORM (Clearly state all pertinent details, and give pertinent dates, including  
estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and  
zones pertinent)

DATE OF WORK

STATUS UPDATE: Currently shut-in pending engineer evaluation.

RECEIVED

NOV 24 1993

COLORADO OIL & GAS CONSERVATION COMMISSION

I hereby certify that the foregoing is true and correct

SIGNED Cami Minzenmayer TELEPHONE NO. (817)877- 6530

NAME (PRINT) Cami Minzenmayer TITLE Regulatory Analyst DATE 10-25-93

This space for Federal or State office use

APPROVED

APPROVED CONDITIONS OF APPROVAL, IF ANY TITLE DATE