

Final Reclamation Inspection

May 13, 2019

Operator: PDC ENERGY INC - 69175

API: 05-001-08667

Inspection Document #: 697500094

Adams County, CO

SENW Section 5 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: DEGENHART #3
API: 05-001-08667



Photo 1. Photo taken from the entrance of location, facing North. Operator has failed to perform final reclamation activities. Photo illustrates gravel which remains at location.

Inspection Photos
Location Name: DEGENHART #3
API: 05-001-08667



Photo 2. Photo taken from the entrance of location. Photo illustrates a culvert which remains at location.



Photo 3. Photo taken from the central location, facing West. See comments under Photo 1. Also, there was unmanaged weeds (Kochia) observed at Location.

Inspection Photos
Location Name: DEGENHART #3
API: 05-001-08667



Photo 4. Photo taken from the central location, facing East. See comments under Photo 1.



Photo 5. Photo taken from the central location. Photo illustrates what appears to be a groundwater monitoring well. Other monitoring wells were observed at location.