

Inspection Photos  
Operator: BP America  
Location/API #: 067-09199  
Date: 5-3-2019



Photo 1. View of the northern project area from the northeastern corner facing westward.





Photo 2. View of musk thistles (*Carduus nutans*) within the interim reclamation area. Approximately 1000 individuals maturing and young seedlings observed.





Photo 3. View of what appears to be unused equipment within the project area.



Photo 4. View of a eference area north of the project area.