

Inspection Photos
Location Name: Ranger 7-14HZ
Location ID: 46290



Photo 1 loc pic



Photo 2 loc pic

Inspection Photos
Location Name: Ranger 7-14HZ
Location ID: 46290



Colorado Oil and Gas Conservation Commission
40.07114, -104.93601, 1543.3m
May 14, 2019 15:03:05

Photo 3 Stained soil



Colorado Oil and Gas Conservation Commission
40.07058, -104.93577, 1529.3m
May 14, 2019 15:04:26

Photo 4 Protection of soils: Material being pushed up on top soil pile.



Inspection Photos
Location Name: Ranger 7-14HZ
Location ID: 46290



Photo 5 Protection of soils and storm water: material being pushed up on top soil pile and also blocking drainage ditch of location. Sediment building up behind pushed up material possible storm water issue.



Photo 6 Loc pic

Inspection Photos
Location Name: Ranger 7-14HZ
Location ID: 46290



Photo 7 Chemical storage



Photo 8 Loc pic

Inspection Photos
Location Name: Ranger 7-14HZ
Location ID: 46290



Photo 9 loc pic