

Inspection Photos

Loc#439603

Operator: Sandridge

Inspection Number: 692400962

Inspection Date: 5/7/19





Photo#1:
Overview of Location to Northeast.

May 7, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Gregory Loc#439603



Photo#2:
Silt fence is installed around perimeter of Location expansion.

May 7, 2019



Photo#3:
Silt fence is installed around perimeter of Location expansion.



Photo#4:

Adjust, install cellar covers/ fencing to maximize safety and wildlife welfare.

May 7, 2019

Photo#5:

Adjust, install cellar covers/ fencing to maximize safety and wildlife welfare.

