

Inspection Photos

5/14/2019

Operator: PCR OPERATING LLC - 10657

Location ID: 454195

Inspection Doc. Number: 696200050

Morgan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 454195



Photo 1: Photo taken from the tank battery. Photo shows signage/labeling has been installed on tanks.



Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 454195



Photo 2: Photo taken from the tank battery, facing southeast. Photo shows secondary containment at battery remains insufficient.



Inspection Photos
Operator Name: PCR OPERATING LLC - 10657
Location ID: 454195



Photo 3: Photo taken from the west end of the location, facing north. Photo shows meter shed where gas is freely venting.

