

Interim Reclamation and Stormwater Inspection

May 6, 2019

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Location ID: 422923

Inspection Document #: 697500111

Weld County, CO

SWSW Section 6 T3N R62W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: FRENCH LAKE 3-62-6 #1H
Location ID: 422923



Photo 1. Photo taken from the southern location, facing North. Operator has performed interim reclamation activities with the evidence of desirable species. However, interim areas have not met reference area vegetative conditions (i.e., lack of shrubs and uniform growth).



Photo 2. Photo taken from the southern location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: FRENCH LAKE 3-62-6 #1H
Location ID: 422923



Photo 3. Reference photo taken south of the location, facing Southeast.