

# Final Reclamation Inspection

May 6, 2019

Operator: NOBLE ENERGY INC- #100322

API: 05-123-21031

Inspection Document #: 697500115

Weld County, CO

SENE Section 27 T4N R63W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: CERVI #42-27  
API: 05-123-21031



**Photo 1.** Photo taken from the northern tank battery location, facing North. Operator has performed final reclamation activities and removed equipment in response to the previous corrective action inspection.

Inspection Photos  
Location Name: CERVI #42-27  
API: 05-123-21031



**Photo 2.** Photo taken from the southern tank battery location, facing South.  
See comments under Photo 1.

Inspection Photos  
Location Name: CERVI #42-27  
API: 05-123-21031



**Photo 3.** Photo taken from the former well location access road, facing West. Operator has repaired erosion along the access road and installed temporary BMPs in response to the previous corrective action inspection.