

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/13/2019

Submitted Date:

05/14/2019

Document Number:

697300064**FIELD INSPECTION FORM**Loc ID 424967 Inspector Name: Graber, Candice (Nikki) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10311Name of Operator: SRC ENERGY INCAddress: 1675 BROADWAY SUITE 2600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Castro, Dave		dcastro@srcenergy.com	
,		cogccinspections@srcenergy.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454240	SPILL OR RELEASE	CL	03/08/2018		-	Ikenouye West Vault	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site condition at the time of inspection.

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Good.

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: NoComment: None observed.☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	454240	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI

--

Environmental**Spill/Remediation:**Comment: [No further action has been approved for Remediation #11108.](#)Corrective Action: [Plug and abandon monitoring wells according to DWR regulations and standard environmental practices within 90 days.](#)Date: 08/12/2019

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697300065	Locatoin Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4823964