

Inspection Photos

Location Name: Aristocrat Angus Gas Plant

Facility ID: 464230



COGCC Environmental Inspection
40.25814, -104.66611, 4744.9ft, 313°
14/05/2019 11:40:31 AM

Photo 1 – Scrap metal, unused equipment, and damaged fencing at north gate.



COGCC Environmental Inspection
40.25831, -104.6663, 4719.3ft, 62°
14/05/2019 12:01:04 PM

Photo 2 – Improperly abandoned soil boring (TH-04) remains unfilled and capped by scrap metal placed by COGCC on 4/24/2019.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Aristocrat Angus Gas Plant

Facility ID: 464230



Photo 3 – Scarred vegetation from recently removed barrels.



Photo 4 – Fencing and electrical equipment remains in place.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Aristocrat Angus Gas Plant
Facility ID: 464230



Photo 5 – RW-01



Photo 6 – RW-02

Inspection Photos
Location Name: Aristocrat Angus Gas Plant
Facility ID: 464230



Photo 7 – MW-01



Photo 8 – MW-03

Inspection Photos
Location Name: Aristocrat Angus Gas Plant
Facility ID: 464230



Photo 9 – MW-05



Photo 10 – MW-07



R000003

Woodward-Clyde Consultants


SOIL
TPH - mg/kg
(BTEX qualified results)

CDOR
FREE PRODUCT

DPH
27 B
258 BTEX TOTAL
4 TPH



SCALE: 1 INCH=100 FEET
100' 0 100'



* RELATIVE ELEVATIONS BASED UPON ASSUMED ELEVATION OF 100 FEET AT MW-03 WELL HEAD.

Job No.: 23495
Prepared by: M.W.Z.

FIGURE 3
FORMER ARISTOCRAT GAS PLANT
SAMPLE LOCATION MAP

Historic Map utilized to find monitoring wells and test borings.