

Final Reclamation Inspection

May 13, 2019

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

API: 05-001-09086

Inspection Document #: 697500117

Adams County, CO

NESE Section 7 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: WIERMAN #43-7 (1)
API: 05-001-09086



Photo 1. Photo taken from the facility/well location, facing West. Well was plugged 2/28/2019. Operator shall remove all equipment within 3 months of plugging (5/28/2019).



Photo 2. Photo taken from the facility/well location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: WIERMAN #43-7 (1)
API: 05-001-09086



Photo 3. Photo taken from the facility/well location, facing Northwest. See comments under Photo 1.



Photo 4. Photo taken from the northern well access road, facing South. Operator shall comply with Rule 1004 to remove the access road.