

Final Reclamation Inspection

May 13, 2019

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

API: 05-001-06862

Inspection Document #: 697500119

Adams County, CO

NENE Section 18 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: GREAT WESTERN FRONT
RANGE #2
API: 05-001-06862



Photo 1. Photo taken from the well location, facing South. Location will remain in-process as it does not meet Rule 1004 standards. Cheatgrass was observed in high densities throughout the well location which is not reflective of reference area vegetation. Reference area vegetation mainly consists of Sand dropseed.

Photo 2. Photo taken from the well location. Photo illustrates weedy annual growth of Cheatgrass.