

Location Name: Husky Hill 10-31

API: 05-103-08022

Inspection: 679704062



Photo 1. Location looking west.

Location Name: Husky Hill 10-31

API: 05-103-08022

Inspection: 679704062



Photo 2. Tank battery.

Location Name: Husky Hill 10-31

API: 05-103-08022

Inspection: 679704062



Photo 3. Oily waste next to vertical separator at tank battery.



Photo 4. Oily waste at truck loading between tank battery and separator.

Location Name: Husky Hill 10-31

API: 05-103-08022

Inspection: 679704062



Photo 5. Missing "Crude Oil" at one tank.